


3312453.016

----- FIELD WIRING  
 \_\_\_\_\_ FACTORY WIRING



NuStart	
1	RUN
N/C	RUN CAP
2	ACTIVE
3	START WINDING
N/C	NOT USED
4	COMMON